



Administrative Record for the US Department of Energy Rocky Flats Index

B800 - Building Cluster B800

Last updated: 10/15/2021

numerical index

B800-A-000001	1/17/2001
Meeting Minutes: Initial Characterization of B800 Area facility project	
Meeting Minutes: The meeting was held to provide initial characterization and scope of the 800 Area facility project and to provide historical information regarding Contaminants of Concern (COC) and facility walk down data. This project includes Buildings 888, 864, 830, 885, 863, S886 and T883D. The Tanks involved in this project are 020, 021 and 026.	
https://lmpublicsearch.lm.doe.gov/SiteDocs/B800-A-000001.PDF	112 KB

B800-A-000002	2/7/2001
Weekly 800 Area Meeting notes	
Purpose of Contact: Weekly 800 Area Meeting notes	
https://lmpublicsearch.lm.doe.gov/SiteDocs/B800-A-000002.PDF	143 KB

B800-A-000006	4/10/2001
Type 1 Facility Closeout Report: Group-B, T881B	
Group-B: Trailer T881B Type 1 Facility Closeout Report. T881B, Office Trailer, formerly located northeast of Building 881 at Rocky Flats Environmental Technology Site (RFETS).	
https://lmpublicsearch.lm.doe.gov/SiteDocs/B800-A-000006.PDF	87 KB

B800-A-000007	6/28/2001
Submits Type 1 RLCR: 800 Area, dated June 15, 2001	
Correspondence and supplemental materials submit the attached 800 Area Reconnaissance Level Characterization Report (RLCR), dated June 15, 2001. Supplemental materials include: e-mail (February 2001) correspondence regarding the Historical Facility Overview; February 1, 2001 Contact Record regarding the Scoping meeting for the 800 Area, Security Area, and the 400/500/900 Area Facilities; January 17, 2001 Interoffice Memorandum regarding the minutes of the Kickoff meeting - 800 Area Facilities - January 8, 2001 and meeting notes.	
https://lmpublicsearch.lm.doe.gov/SiteDocs/B800-A-000007.PDF	8 MB

B800-A-000008	6/15/2001
RLCR 800 Area Type 1 Cluster Closure Project, dated July 15, 2001	
Reconnaissance Level Characterization Report (RLCR) 800 Area Type 1 Cluster Closure Project (Buildings 830, 863, 864, 885, T883D, and Tanks Slabs 020, 021, and 026) Revision 0, dated June 15, 2001. The purpose of this report is to communicate and document the results of the RLC effort. Before the facilities can be removed, a Pre-Demolition Survey (PDS) must be conducted; this document presents the PDS results. PDSs are performed before building demolition to define the final radiological and chemical conditions of a facility. Final conditions are compared with the release limits for radiological and non-radiological contaminants. PDS results will enable project personnel to make final disposition decisions, develop related worker health and safety controls, and estimate waste volumes by waste types. Includes Attachment A: Facility Location Map; Attachment B: Historical Site Assessment (HSA) Reports; Attachment C: Radiological Characterization Package; Attachment D: Chemical Characterization Package; Attachment E: Radiological Data Summaries and Survey Maps; Attachment F: Chemical Data Summaries and Sample Maps; Attachment G: Decommissioning Waste Types and Volume Estimates; Attachment H: Data Quality Assessment (DQA) Detail.	
https://lmpublicsearch.lm.doe.gov/SiteDocs/Revised_B800-A-000008.pdf	6 MB
B800-A-000009	8/9/2001
Forwards the 800 Area RLCR: Bldgs 830, 863, 864, 885, T883D; July 15, 2001	
US Department of Energy, Rocky Flats Field Office (DOE/RFFO) forwards the Reconnaissance Level Characterization Report (RLCR) for the 800 Area Type 1 Cluster, dated July 15, 2001. [Buildings 830, 863, 864, 885, Trailer T883D, and Tank Slabs 020, 021, and 026]	
https://lmpublicsearch.lm.doe.gov/SiteDocs/B800-A-000009.PDF	88 KB
B800-A-000010	2/5/2001
Meeting Minutes Internal/External Scoping 800 Area, Security Area 400/500/900 Area	
Meeting Minutes of the Internal/External Scoping for the 800 Area, Security Area and the 400/500/900 Area dated February 1, 2001. Also attached is a Regulatory Contract Record, which also discusses these areas. The initial characterization and scoping of these areas is to provide historical information regarding Contaminants of Concern (COC) and facility walk down data.	
https://lmpublicsearch.lm.doe.gov/SiteDocs/B800-A-000010.PDF	256 KB
B800-A-000011	2/1/2001
Scoping Meeting for the 800 Area	
Purpose of Contact: Scoping Meeting for the 800 Area, Security Area and the 400/500/900 Area Facilities. This also includes Kaiser-Hill Company, L.L.C. (K-H) Minutes of the Internal/External Scoping of 800 Area, Security Area, and the 400/500/900 Area.	
https://lmpublicsearch.lm.doe.gov/SiteDocs/B800-A-000011.PDF	378 KB
B800-A-000012	9/20/2001
General 800 Area Scoping Meeting	
Purpose of Contact: General 800 Area Scoping Meeting. Discusses the Radiological Characterization Plan and the Chemical Characterization Plan for T891G, T891O, T891R and T891V, which was delivered to the attendees for information. Kaiser-Hill Company, L.L.C. (K-H) will differentiate the facilities to be characterized on the General 800 List.	
https://lmpublicsearch.lm.doe.gov/SiteDocs/B800-A-000012.PDF	109 KB

B800-A-000013	10/11/2001
RLCR for 800 Area Type 1 Cluster Closure Project Buildings - Concurrence	
The Colorado Department of Public Health and Environment (CDPHE) has reviewed the Reconnaissance Level Characterization Report (RLCR) for the 800 Area Type 1 Cluster Project Buildings, Revision 0. Based on the information contained in the RLCR, we are concurring with the Type 1 designation.	
https://lmpublicsearch.lm.doe.gov/SiteDocs/B800-A-000013.PDF	83 KB
B800-A-000014	3/6/2001
Historical Site Assessment for RLCR 800 Area	
Historical Site Assessment (HSA) for Reconnaissance Level Characterization Report (RLCR) 800 Area Type 1 Cluster Closure Project Revision 0, June 15, 2001.	
https://lmpublicsearch.lm.doe.gov/SiteDocs/B800-A-000014.PDF	7 MB
B800-A-000015	2/20/2001
Chemical Characterization Package 800 Area Type 1 Cluster Closure Project	
Chemical Characterization Package 800 Area Type 1 Cluster Closure Project Revision 1, February 20, 2001.	
https://lmpublicsearch.lm.doe.gov/SiteDocs/Revised_B800-A-000015.pdf	12 MB
B800-A-000016	3/1/2001
Radiological Characterization Package 800 Area Cluster Project	
Radiological Characterization Package 800 Area Cluster Project Revision 1 (was Revision 0, revised October 22, 2001), March 1, 2001.	
https://lmpublicsearch.lm.doe.gov/SiteDocs/B800-A-000016.PDF	663 KB
B800-A-000017	4/15/2002
Type 1 Facility Closeout Report: T883D Rest Room Support Trailer Facility, 200 SF	
Type 1 Facility Closeout Report - T883D Rest Room Support Trailer Facility, 200 SF - Includes a letter from the Colorado Department of Public Health and Environment (CDPHE) concurring with the Reconnaissance Level Characterization Report (RLCR) for the 800 Area Type 1 Cluster Closure Project. (Attached is a US Government Certificate to Obtain Title to Vehicle) (RISS Facility)	
https://lmpublicsearch.lm.doe.gov/SiteDocs/B800-A-000017.PDF	304 KB
B800-A-000018	1/1/2001
Type 1 Facility Closeout Report: S886 Bus Stop Pool Shelter Waiting Facility	
Type 1 Facility Closeout Report - S886 Bus Stop Pool Shelter Waiting Facility (RISS Facility)	
https://lmpublicsearch.lm.doe.gov/SiteDocs/Revised_B800-A-000018.pdf	547 KB

B800-A-000019	4/15/2002
Type 1 Facility Closeout Report: Group-B T881B Office Facility	
Type 1 Facility Closeout Report - Group-B T881B Office Facility - Includes a letter from the Colorado Department of Public Health and Environment (CDPHE) concurring with the Reconnaissance Level Characterization Report (RLCR) for Group-B Type 1 designation. (Attached is a US Government Certificate to Obtain Title to Vehicle) (RISS Facility)	
https://lmpublicsearch.lm.doe.gov/SiteDocs/B800-A-000019.PDF	315 KB
B800-A-000020	1/15/2003
Requests permission to remove process alarm equipment 800-area	
Purpose of Contact: Requests permission to remove the process alarm equipment in the 800-area Valve Vaults as the net step in the closure. Requests permission to begin work on clean closure of the new process waste line between Building 866 and Valve Vault 6.	
https://lmpublicsearch.lm.doe.gov/SiteDocs/B800-A-000020.PDF	1 MB
B800-A-INFO	1/9/2001
Note to File: Includes: B888, 864, 830, 885, 863, S886, T883D, and Tanks 020, 021, 026.	
800 Area Project: This project includes the following facilities and Tanks: Buildings 888, 864, 830, 885, 863, S886 (Bus Stop Shelter), Trailer T883D, and external Tanks 020, 021, and 026. Note that 888 and the 886 Guard Shack are also included in the 886 Cluster IM/IRA - Guidance as to whether these buildings will be characterized under the 800 Area Project or the 886 Cluster is expected.	